## **DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 1.28

# WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-000700 Address: 333 Burma Road **Date Inspected:** 26-Oct-2007

City: Oakland, CA 94607

**Project Name:** SAS Superstructure **OSM Arrival Time:** 630 **OSM Departure Time:** 1430 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

American Bridge/Fluor (ABF) Contractor: **Location:** Benicia, CA

**CWI Name:** Bill Norris **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A **Qualified Welders:** Yes No N/A **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:** 

34-0006 **Bridge No: Component: PQR** Test Plate

### **Summary of Items Observed:**

Caltrans QA Inspector, Ken Jobes, observed the fit-up and welding of ABF-PQR-027-2A at the Ironworker's Apprentice Training Facility in Benicia, CA. American Welding Society (AWS) Certified Welding Inspector (CWI), Bill Norris (CWI No. 90011341) was present during this test. Bill Norris recorded all applicable parameters. This test plate was welded in the overhead (4G) welding position. See TL 6032 generated on this date. Test plate is to be ground flush and ultrasonically examined for information purposes and then shipped for radiography.

#### **Summary of Conversations:**

Caltrans QA Inspector informed the QC Inspector that Lot. No. B93-008-07 will be assigned to PQR-027-2A.

#### **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh, (818) 292-0659, who represents the Office of Structural Materials for your project.

**Inspected By:** Jobes, Kenneth **Quality Assurance Inspector** 

**Reviewed By:** Mertz, Robert **QA** Reviewer